

Model : Panasonic EtherCAT Servo Drive MINAS-A5B series

Model Name : M\*DHT\*\*\*\*B01/M\*DHT\*\*\*\*BA1/M\*DHT\*\*\*\*B21/M\*DHT\*\*\*\*BD1

Update Dates : Ver3.04 / Product at Factory from January 2016 or later

Latest firmware version : Ver3.04 (Object 3744h = 03040304h)  
Previous firmware version : Ver3.02 (Object 3744h = 03020302h)

This changes does not effect to ESI file.

Please check the details from Panasonic Web-site.

<http://industrial.panasonic.com/ww/products/motors-compressors/fa-motors/ac-servo-motors#MINASA5B>

No	Functions	Related Parameters	Related Objects	Related Alarms 603Fh-00h(Error code) 10F3h(Diagnosis history) 1001h-00h(Error register)
1	<b>【Servo Function Update】</b> Home position reference trigger (HOME, POT, NOT, EXT1, EXT2) b-contact setting function	•Pr4.04(SI5 input selection) •Pr4.05(SI6 input selection) •Pr4.06(SI7 input selection)	•3404h-00h(SI5 input selection) •3405h-00h(SI6 input selection) •3406h-00h(SI7 input selection)	•Latch input allocation error protection (Err33.8)
2	<b>【EtherCAT Function Update】</b> Supports Clearing multi-turn data via EtherCAT	•Pr0.15(Absolute encoder setup)	•3015h-00h(Absolute encoder setup)  •4D00h-00h(Number of entries) •4D00h-01h(Special function start flag 1) •4D00h-02h(Special function start flag 2) •4D01h-00h(Special function setting 9)	•Absolute system down error protection (Err40.0) •Absolute clear protection (Err27.1) ※This error does no occurred via EtherCAT command
3	<b>【EtherCAT Function Update】</b> Supports Read warning code via EtherCAT	•Pr6.37(Oscillation detection level) •Pr6.38(Warning mask setting) •Pr7.14(Main power off warning detection time)	•603Fh-00h(Error code) •3637h-00h(Oscillation detecting level) •3638h-00h(Alarm mask setup) •3714h-00h(Main power off warning detection time)	–
4	<b>【Servo Function Update】</b> Supports Homing return speed limit function	•Pr7.22(Communication function Extended setup 1) bit6 : Homing return speed limit function enabled 0:Invalid 1:Valid •Pr7.93(Homing return limit speed)	•3722h-00h(Communication function extended setup 1) •3793h-00h(Homing return speed limit value)	–
5	<b>【Servo Function Update】</b> Supports monitoring over load factor on 7-segment LED	•Pr7.00(Information on LED)	•3700h-00h(Display on LED)	–
6	<b>【EtherCAT Function Update】</b> Supports Over load factor monitor via EtherCAT	–	•4D29h-00h(Over load factor)	–

対象モデル	:	パナソニック EtherCAT 対応サーボアンプ MINAS-A5B シリーズ
対象機種名	:	M*DHT****B01/M*DHT****BA1/M*DHT****B21/M*DHT****BD1
更新時期	:	Ver3.04 / 2016年1月以降生産分
最新ファームウェアバージョン	:	Ver3.04 (Object 3744h = 03040304h)
更新前ファームウェアバージョン	:	Ver3.02 (Object 3744h = 03020302h)

この変更においては、ESIファイルに影響はありません。

詳細については、弊社Webサイトから最新資料をダウンロードください。

<http://industrial.panasonic.com/jp/products/motors-compressors/fa-motors/ac-servo-motors#MINASA5B>

No	機能	関連パラメータ	関連オブジェクト	関連アラーム ※アラーム関連オブジェクト 603Fh-00h(Error code) 10F3h(Diagnosis history) 1001h-00h(Error register)
1	【サーボ機能追加】 原点基準トリガ (HOME,POT,NOT,EXT1,EXT2) b接設定機能	・Pr4.04(SI5入力選択) ・Pr4.05(SI6入力選択) ・Pr4.06(SI7入力選択)	・3404h-00h(SI5 input selection) ・3405h-00h(SI6 input selection) ・3406h-00h(SI7 input selection)	・ラッチ入力割付異常保護(Err33.8)
2	【EtherCAT機能追加】 EtherCAT経由 アブソリュートエンコーダ設定 エンコーダ多回転クリア機能	・Pr0.15(アブソリュートエンコーダ設定)	・3015h-00h(Absolute encoder setup)  ・4D00h-00h(Number of entries) ・4D00h-01h(Special function start flag 1) ・4D00h-02h(Special function start flag 2) ・4D01h-00h(Special function setting 9)	・アブソリュートエンコーダ多回転クリアでは 発生しない
3	【EtherCAT機能追加】 EtherCAT警告読み出し機能	・Pr6.37(発振検出レベル) ・Pr6.38(警告マスク設定) ・Pr7.14(主電源オフ警告検出時間)	・603Fh-00h(Error code) ・3637h-00h(Oscillation detecting level) ・3638h-00h(Alarm mask setup) ・3714h-00h(Main power off warning detection time)	—
4	【サーボ機能追加】 原点復帰戻り動作時の異音対策	・Pr7.22(通信機能拡張設定1) bit6 : 原点復帰戻り動作速度制限機能有効化 0:無効 1:有効 ・Pr7.93(原点復帰戻り動作制限速度)	・3722h-00h(Communication function extended setup 1) ・3793h-00h(Homing return speed limit value)	—
5	【サーボ機能追加】 前面パネル7セグLED オーバーロード負荷率モニタ機能	・Pr7.00(LED表示内容)	・3700h-00h(Display on LED)	—
6	【EtherCAT機能追加】 EtherCAT経由 オーバーロード負荷率モニタ機能	—	・4D29h-00h(Over load factor)	—