

Update information (Jun.1.2015 update)

Software ver.1.02.0015/2.02.0015 → 1.02.0023/2.02.0023

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.02.0023
	Installer for 64bit version	2.02.0023
PANATERM	PANATERM main body	5.0.3.15
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	Updated define files for MINAS-A5II, MINAS-A5B, MINAS-A5L04(A4), MINAS-A5ND1 and MINAS-A5NL series.
2	PANATERM	Updated operation manual to the latest data.
3	PANATERM	Updated layout of Selection of the communication with the driver screen.
4	PANATERM	Updated layout of Measure Item Select screen of Wave form graphic.
5	PANATERM	The 4 defects below were revised.

● History of correction

No	Function	Phenomenone
1	Parameter	Revised on the point that sometimes the different set value is displayed after writing to EEPROM.
2	Wave form graphic	Revised on the point that the collective button is displayed different language after changing the language.
3	Additional series type setting	Revised on the point that sometimes PANATERM is freezed by failure of updating the series definition file.
4	Trial run	Revised on the point that the motor do not run the operation area Min./Max..