

PANATERM Ver6.0

Update information (Software ver.6.0.9.1 → 6.0.10.0)

● Version information

Item	Contents	Version
Setup	Installer	6.10.0
PANATERM	PANATERM main body	6.0.10.0
ParameterConverter	Parameter file conversion software	1.1.0
SimMotor	Software for simulation	2.1.0
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	16.00.0000
	Installer 64 bit version for USB communication device driver	16.02.0000
USBDriver	Device driver for 32 bit version USB communication	1.1.0.0
	Device driver for 64 bit version USB communication	1.1.0.0
Operation manual	Set up support software PANATERM Ver. 6.0	3.19

● History of change point

No	Objects	Contents
1	PANATERM	Added "Twisted table compensation (Absolute precision improving)"
2	PANATERM	Supported MINAS-A6B series Ver1.15 driver
3	PANATERM	Supported MINAS-A6S series Ver1.15 driver

● History of correction

No	Function	Symptoms
1	Parameter	Fixed "PANATERM is forced to terminate when a maximizable screen is started while the Parameter screen is maximized".
2	Monitor	Fixed "Wrong dialog appears when EEPROM fails".
3	Object Editor Monitor	Fixed "In the Set Home function, when the driver disconnects and then reconnects while displaying the dialog notifying writing to "607Ch-00h, the writing process is not interrupted".
4	Monitor	Fixed "In the Set Home function, if the driver disconnects while displaying the EEPROM dialog and then reconnects and presses the OK button, the write process is not interrupted".
5	Common	Fixed "When the driver disconnects communication while displaying the EEPROM dialog with Monitor screen, and then reconnects and presses the OK button, the write process is not interrupted".
6	Block operation Editor v2	Fixed "If the language setting for PANATERM is set to a language other than Japanese and MINAS-A6ST is selected, an error occurs when the Block operation Editor v2 is started".