

About abnormal start-up of Windows PANATERM

Motor Business Unit
Automotive & Industrial Systems Company
Panasonic Corporation

About abnormal start-up of Windows PANATERM

Target : Windows PANATERM5.0 or later (MINAS-A5/A6 Family)

Phenomenon :

After Windows update on Oct .10 , Some PCs can not operate PANATERM normally.

Targets of Windows OS Version and update program

Windows OS	Update program
Windows 7	KB4041681
Windows 8.1	KB4041693
Windows 10	KB4041676 (Version 1703)
	KB4041691 (Version 1607)
	KB4041689 (Version 1511)
	KB4042895 (Version 1507)

Measure :

Update to the latest PANATERM(Ver.6.0.1.7 or later).

<https://www3.panasonic.biz/ac/e/motor/fa-motor/ac-servo/panaterm/index.jsp>

Other measures are below.

- 1.Use PCs that are not applied with targeted update program.
- 2.Delete targeted update program.