Update information
(Software ver.1.03.0020/2.03.0022 → 1.03.0021/2.03.0023)

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.03.0021
	Installer for 64bit version	2.03.0023
PANATERM	PANATERM main body	6.0.1.16
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0
Operation manual	Set up support software PANATERM Ver. 6.0	3.07

● History of change point

No	Objects	Contents
1	PANATERM	We enabled wireless communication in the United States, Korea, and Taiwan.
2	Operation	Updated operation manual to the latest data.
3	PANATERM	The 2 below were fixed.

● History of correction

No	Function	Symptoms
1	Fit gain (2 degrees of freedom control)	Clarified the selected cell in the manual selection tab of Step5.
2	Selection of the communication with the driver	Fixed that RS232/RS485 communication may not be possible. .