

Update information (Mar 3, 2017 update)
Software ver. 1.03.0001/2.03.0001 → 1.03.0004/2.03.0004

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.03.0004
	Installer for 64bit version	2.03.0004
PANATERM	PANATERM main body	6.0.1.2
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device	1.00.0000
	Installer 64 bit version for USB communication device	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	Updated define files for MINAS-A6N series.
2	PANATERM	The 5 defect below were revised.

● History of correction

No	Function	Phenomenone
1	Monitor	Revised on the point that High / Low count of Digital input / output signal monitoring may not be displayed correctly in MINAS-A6N series.
2	Wave form graphic	Revised on the point that sometimes the exception happens when get the measurement results.
3	File save	Revised on the point that a new line can be not enter at the beginning in comment.
4	Frequency characteristics	Revised on the point that the measurement results may not be acquired correctly in MINAS-A6N series.
5	Trial run	Revised on the point that sometimes it servo off when operation is started after Mode error cancellation.