

## Update information (May 22, 2018 update)

Software ver.1.03.0012/2.03.0013 → 1.03.0014/2.03.0015

### ● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.03.0014
	Installer for 64bit version	2.03.0015
PANATERM	PANATERM main body	6.0.1.10
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0
Operation manual	Set up support software PANATERM Ver. 6.0	3.03

### ● History of change point

No	Objects	Contents
1	PANATERM	Additional support for drivers MINAS-A6 (V-frame) series.
2	PANATERM	Additional support for drivers MINAS-A6N series Ver1.23.
3	PANATERM	Additional support for drivers MINAS-A5BL series Ver8.01.
4	PANATERM	Updated def files for MINAS-A6B series.
5	Operation manual	Updated operation manual to the latest data.
6	PANATERM	The 3 symptoms have been modified as follows.

### ● History of correction

No	Function	Symptoms
1	Parameter	Correct the symptoms that the exception error sometimes occur when the combo box is displayed.
2	Pin Assign	Correct the typographical error in the dialog message. (In English only)
3	Object editor	Correct the symptoms that wrong values are sometimes substituted for the object of the 607Eh-00h Polarity in the MINAS-A6B series.