

**Update information (Apr 28, 2017 update)**  
**Software ver.1.03.0004/2.03.0004 → 1.03.0006/2.03.0006**

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.03.0006
	Installer for 64bit version	2.03.0006
PANATERM	PANATERM main body	6.0.1.4
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	Added support for drivers MINAS-A6B series.
2	PANATERM	The 1 defect below were revised.

● History of correction

No	Function	Phenomenone
1	Wave form graphic	Revised on the point that sometimes the exception happens when communication restart.