




1. Discontinue products in 2015

• Relays

| Products name | Types | Part no. | Substituted products name | Substituted part no. | Reason and remarks | Last time buy |
|--|------------------------------------|--------------------------------|---|--------------------------------|---|-------------------|
| DS relays (2 Form C type) (made in Japan)  | 400mW nominal operating power type | DS2E-M-DC00V DS2E-ML2-DC00V | DS relays High sensitivity type (200mW nominal operating power type) (made in China) | DS2E-S-DC00V DS2E-SL2-DC00V | Product type unification to high sensitivity type | End of March 2015 |
| DS relays (2 Form C type) (made in Japan)  | Reverse polarity type | DS2E-000-DC00V-R | None | — | Less needs caused by decreasing demand | End of March 2015 |

*Special order products and set products related to the above products are scheduled to be discontinued at the same time.







• Switches

| Products name | Types | Part no. | Substituted products name | Substituted part no. | Reason and remarks | Last time buy |
|--|----------|------------|---------------------------|----------------------|--|-------------------|
| AM5(QV) Switches  | All type | AM50000000 | None | — | Difficulty of business continuation (For detail, please see Automation News T-1334 issued in April, 2014) | End of March 2015 |

*Special order products and set products related to the above products are scheduled to be discontinued at the same time.

1. Discontinue products in 2015

• Connectors

| Products name | Types | Part no. | Substituted products name | Substituted part no. | Reason and remarks | Last time buy |
|---|--|--|----------------------------------|--|--|-----------------------|
|  <p>LED Lighting Terminal L1</p> | All type | AYL111240 (Receptacle) AYL121240 (Joint plug) | None | — | Less needs caused by decreasing demand | End of September 2015 |
|  <p>Micro Coaxial Connectors CS</p> | All type | AXC51S00000 (Receptacle) AXC61S00000 (Plug) AXC81S00000 (Plug cover shell) | None | — | Less needs caused by decreasing demand | End of September 2015 |
|  <p>Micro Coaxial Connectors CF</p> | All type | AXC51F4040 (Receptacle) AXC61F4040 (Plug) AXC81F40410 (Plug cover shell) | None | — | Less needs caused by decreasing demand | End of September 2015 |
|  <p>Narrow Pitch Connectors F4</p> | All type | AXK7L00000 (Socket) AXK8L00000 (Header) | None | — | Less needs caused by decreasing demand | End of September 2015 |
|  <p>Narrow Pitch Connectors P4S</p> | With pickup cover | AXT300064 (Socket) AXT3E0066 (for socket inspection usage) AXT400064 (Header) AXT4E0066 (for header inspection usage) | Without pickup cover | AXT300024 (Socket) AXT3E0026 (for socket inspection usage) AXT400024 (Header) AXT4E0026 (for header inspection usage) | Product type unification to without pickup cover type | End of September 2015 |
|  <p>Narrow Pitch Connectors A4S (Sockets only)</p> | Contact material Titanium Copper Alloy | AXE500124 (Socket) | Contact material Phosphor Bronze | AXE500127 (Socket) | To promote procurement of versatile materials for contacts (For detail, please see Automation News T-1322 issued in September, 2013) | End of September 2015 |

*Special order products and set products related to the above products are scheduled to be discontinued at the same time.