

## Discontinue products in 2018




### • Relays

Products name	Types	Part no.	Substituted products name	Substituted part no.	Reason and remarks	Last time buy
 <p>HC relays</p>	All type	HC000-000-AC000V-0 HC000-000-DC000V-0 HC0-0-DC000V-0-0	None	None	Due to business termination of H series Control Panel Relays	End of September 2018
 <p>HJ relays</p>	All type	HJ0-0-DC000V-0-6 HJ0-0-AC00000000V-0-6 HJ0-0-0-DC000V-0 HJ0-0-0-AC00000000V-0	None	None	Due to business termination of H series Control Panel Relays	End of September 2018
 <p>HL relays</p>	All type	HLO-000-DC000V-0 HLO-000-AC000V-0	None	None	Due to business termination of H series Control Panel Relays	End of September 2018
 <p>HC relay accessories (Socket, DIN terminal socket and Leaf spring)</p>	All type	HC0-00-0 HC0-000-0 HC/HL-LEAF-SPRING-MK HC-LEAF-SPRING-K	None	None	Due to business termination of H series Control Panel Relays	End of September 2018
 <p>HJ relay accessories (Socket and DIN terminal socket)</p>	All type	HJ0-000-0 HC0-00-0-H105 HC0-000-0 HL-LEAF-SPRING-K	None	None	Due to business termination of H series Control Panel Relays	End of September 2018
 <p>HL relay accessories (Socket, DIN terminal socket and Leaf spring)</p>	All type	HLO-00-K AHKA210 HC/HL-LEAF-SPRING-MK	None	None	Due to business termination of H series Control Panel Relays	End of September 2018

\*Special order products and set products related to the above products are scheduled to be discontinued at the same time.


## Discontinue products in 2018

### • Relays

Products name	Types	Part no.	Substituted products name	Substituted part no.	Reason and remarks	Last time buy
 SSR	AQC Relays	AQC○○○○	None	None	Due to reduced market demand for this product with no anticipated increase	End of September 2018
 SSR	AQ Relays	AQ1AD2-3/28VDC AQ2AD1-3/28VDC	None	None	Due to reduced market demand for this product with no anticipated increase	End of September 2018
 SSR	Heat sink	AQP-HS-20A AQP-HS-40A AQP-HS-N40	Heat sink (Same shape)	AQP-HS-J10A AQP-HS-30/40A AQP-HS-J25A	To unify product type	End of September 2018



\*Special order products and set products related to the above products are scheduled to be discontinued at the same time.

### • Switches

Products name	Types	Part no.	Substituted products name	Substituted part no.	Reason and remarks	Last time buy
 AM1(NZ) switches	All type	AM1○○○F	None	None	Due to reduced market demand for this product with no anticipated increase	End of September 2018

\*Special order products and set products related to the above products are scheduled to be discontinued at the same time.

### • Connectors

Products name	Types	Part no.	Substituted products name	Substituted part no.	Reason and remarks	Last time buy
 Narrow pitch connectors P8	All type	AXN3○○○○○○○ (Socket) AXN4○○○○○○○ (Header)	None	None	Less needs caused by decreasing demand and difficulty of business continuation	End of September 2018
 FPC Connector Y5BW	With slits in the molded part	AYF53○○65	No slits in the molded part	AYF53○○65T	To increase the size of the pickup area (Automation News T-1317, September, 2013)	End of September 2018

\*Special order products and set products related to the above products are scheduled to be discontinued at the same time.