


A Benefit by 2-Degree-Of-Freedom (2-DOF) Control

An Example of Milling (CNC Machine Tool)

Conventional
Control



Stripes disappear
& Glossier surface

2-DOF
Control

