# NAIS Automation News

# Components

T-672 Sep. 29, 2000

### Announcement of discontinued production

We would like to inform you of the discontinued products as below.

- 1. Already discontinued products
- 2. Discontinued products in 2001

#### 1. Already discontinued products

#### Relays

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
NF relays MBB type	NFOEB-2M-OOV NFOEB-4M-OOV	TQ relays MBB type	TQ2-2M-OOV	Less needs caused by decreasing demand	Discontinued from Aug. 2000
I/O board	AQ680000 AQ681000 AQ682000	None	_	Less needs caused by decreasing demand	Discontinued from Aug. 2000
Sensitive hybrid relay	AGH1029	None	_	Less needs caused by decreasing demand	Discontinued from Aug. 2000



# Matsushita Electric Works, Ltd.

#### AUTOMATION CONTROLS COMPANY

- Head Office: 1048, Kadoma, Kadoma-shi, Osaka 571-8686, Japan
- Telephone: Japan (81) Osaka (06) 6908-1050
- Facsimile: Japan (81) Osaka (06) 6908-5781

#### Switches

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
WS switches	AWS1000 AWS9000	None	_	Less market needs and decreasing demand	Discontinued from Aug. 2000
GU switches	AVG4OOO	FU switches	AV4OOO	FU switches cover all the types of GU switches and they have superior characteristics.	Discontinued from Aug. 2000
Hook switches	CCC8VA	None	_	Less market needs and decreasing demand	Discontinued from Aug. 2000
J3 Toggle Switches	AJ3OOO	J4 Toggle Switches T-10 Series Switches T-15 Series Switches	AJ4000 T0100000 T0150000	J4 Toggle T-10 series, T-15 series Switches cover J3 Toggle Switches on characteristics.	Discontinued from Aug. 2000
J2 slim paddle-actuator type switches	AJ2SOOO	None	_	Less market needs and decreasing demand	Discontinued from Aug. 2000

#### • Connectors

•••••••					
Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
Narrow-pitch connectors Feed-through type	AXK2OOO	None	_	Less market needs and decreasing demand	Discontinued from Aug. 2000

#### • Pressure sensors

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
PF-A Pressure sensor					
	ADP2OOO	None	_	Less market needs and decreasing demand	End of May. 2001

#### • PLC/I.O.P.

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
PLC FP5 series	AFP5OOO	Programmable controllers FP3 series FP2 series	AFP3OOO AFP2OOO	Discontinued electronic parts, decreasing demand and release of new products	Discontinued from Aug. 2000
PLC FP10	AFP6241000 AFP6251000	Programmable controllers FP10SH series FP2 series	AFP621100 AFP622100 AFP2000	Discontinued electronic parts, decreasing demand and release of new products	Discontinued from Aug. 2000

#### • PLC/I.O.P.

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
I.O.P. B01, M01, D01		Programmable display GT10			
快速を科学します	AIB10000 AIP1000 AID1000		AIGT1000B	Discontinued electronic parts	Discontinued from May. 2000

#### • IMAGE CHECKER

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
Color IMAGE CHECKER	CCC11HNA CCC11HNA	None	None	Discontinued electronic parts and decreasing overseas demand	Discontinued from Aug. 2000
IMAGE CHECKER 30 series	ANB3OOO	None	None	Discontinued electronic parts and new products released	Discontinued from Aug. 2000
IMAGE CHECKER B110 series	ANB10000	None	None	Discontinued electronic parts and new products released	Discontinued from Aug. 2000
Color select unit	ANB7116OO ANB7116OOO	None	None	Discontinued electronic parts and new products released	Discontinued from Aug. 2000
IMAGE CHECKER G110 series	ANG11000	None	None	Discontinued electronic parts and new products released	Discontinued from Aug. 2000

#### • Laser sensor

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
LM100 Laser analog sensor (Invisible type)	ANL1000C	LM100 visible red type or LM10 laser sensor	ANL1OORC or ANROOO	Discontinued electronic parts	Discontinued from Aug. 2000
LM200 Laser analog sensor (Invisible type)	ANL2OOOC	LM200 visible red type or LM10 laser sensor	ANL2OORC or ANROOO	Discontinued electronic parts	Discontinued from Aug. 2000
LM 300 Laser analog sensor (Invisible type)	ANL3OOC	LM300 visible red type	ANL3OOORC	Discontinued electronic parts	Discontinued from Aug. 2000
MQ Laser analog sensor	AN6OOO	LM10 Laser sensor	ANROOO	Discontinued electronic parts	Discontinued from Aug. 2000

#### • Counters

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
LC24 Electronic counters		LC2H Electronic counters			
COUNTER LC24	AEL2	COUNTER LC2H RSST NAIS	AEL3	Changeover is possible due to the release of the LC2H Electronic counter in response tomarket needs.     Production of the micro computer suspended.	Discontinued from Sep. 2000

#### • Hour Meters

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
LH24 Hour Meters  HOUR METER LH24  LH24  LH24	ATH2	LH2H Hour Meters  HOUR METER LH2H  PRISET h m s  NAIS	АТН3	Changeover is possible due to the release of the LH2H Hour Meter in response to market needs. Production of the micro computer suspended.	Discontinued from Sep. 2000

## 2. Discontinued products in 2001

• Relays

Your order-in will be processed until 3 months before phase-out schedule.

• Kelays		our order-in will be	processed until 3 months before	pnase-out schedule.	
Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
HZ relays	HZ1a-OOV-W	EP relays 60A type	AEP160OO	Less needs caused by decreasing demand	Aug. 2001
HX relays surface-mount terminal type	HX2\$A-OOV-O	TX relays surface-mount terminal type	TX2SA-OOV-O	Less needs caused by decreasing demand	Aug. 2001
JT relays open type	JTO-OOV	None	_	Less needs caused by decreasing demand	Aug. 2001
HP relays solder terminal socket for rectangular hold boring	HPO-SRS	HP relays solder terminal socket for rectangular hold boring (with UL/CSA)	HPO-SRS*	Unified to UL/CSA approved type	Aug. 2001
HP relays screw terminal socket	HPO-SF	HP relays screw terminal socket for DIN rail assembly (with UL/CSA)	HPO-SFD <sup>*</sup>	Unified to DIN rail screw terminal socket with UL/CSA	Aug. 2001
HP relays screw terminal socket for DIN rail assembly	HPO-SFD	HP relays screw terminal socket for DIN rail assembly (with UL/CSA)	HPO-SFD <sup>*</sup>	Unified to UL/CSA approved type	Aug. 2001
HG relays screw terminal socket	HGO-SF	HG relays screw terminal socket for DIN rail assembly (with UL/CSA)	HGO-SFD*	Unified to DIN rail screw terminal socket with UL/CSA	Aug. 2001
HG relays screw terminal socket for DIN rail assembly	HGO-SFD	HG relays screw terminal socket for DIN rail assembly (with UL/CSA)	HGO-SFD*	Unified to UL/CSA approved type	Aug. 2001

\*Part No. suffix "-UL" is needed when oprdering.

#### Switches

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
GV switches	AH4OOO	QV micro switches	AM5OOO	QV switches cover all the types of GV switches and they have superior characteristics	End of Aug. 2001
J7 switches momentary type	AJ7129B01	J7 switches	AJ7000	The market require for momentary function. *<0N>-OFF-<0N> is rare. Please recommend customers for J7 switches ON-OFF type. *< > indicates momentary position	End of Aug. 2001
New J9 switches 16A type	AJ91500 ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○	J9 switches	AJ91100000 AJ91110000 AJ92100000 AJ92110000	As new J9 switches have PC board and soldering terminal of 21 A rating which is superior to J9 switches of 16 A rating. However, the lineup of J9 switches is more than New J9 switches, and, the market require for 21 A rating is rare.	End of Aug. 2001
FJ switches mounting hole 1.2mm type AH1100 AH1200	AH11000 (Solder terminal) AH12000 (PC board terminal)	FJ switches mounting hole 2mm type	AH14OOO AH16OOO	Decreasing demand as mounting hole 2.0mm type is the trend	End of Aug. 2001

#### • Connectors

Your order-in will be processed until 3 months before phase-out schedule.

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
SO-DIMM socket	AXA110T	None	_	Less market needs and decreasing demand	End of Aug. 2001
ISA-bus standards card	AXC498801	None	_	Less market needs and decreasing demand	End of Aug. 2001
HB relays socket AXS10HB11, AXS10HB21	AXS10HB11 AXS10HB21	None	_	Discontinued HB relays	End of Aug. 2001
DR relays socket AXS10DR11, AXS10DR12	AXS10DR11 AXS10DR12	None	_	Discontinued DR relays	End of Aug. 2001

#### • Pressure sensor

Your order-in will be processed until 3 months before phase-out schedule.

	processed dritti e montrio before	priace car correaale.			
Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
PV pressure sensors	ADP3OOO	PF pressure sensor	ADP1000	Because the PF pressure sensor can basically cover the market need.	End of Aug. 2001